Repkord

Installing CR30 X-Rail Upgrade Kit 1: Main Assembly

This guide will go through the steps required to upgrade your Creality CR-30 PrintMill's X-Axis from the stock v-wheel mechanics to linear rail.

Written By: Pooch

This document was generated on 2021-12-24 08:05:29 PM (MST).

© 2021   repkord.dozuki.com/   Page 1 of 3

TOOLS:

- 4mm Hex / Allen Key (1)
- 3mm Hex / Allen Key (1)
- 2.5mm Hex Key (1)
- 2mm Hex / Allen Key (1)
- 1mm Hex / Allen Key (1)
- Needle Nose Pliers (1)

PARTS:

- Repkord CR-30 X-Rail Upgrade Kit (1)

This document was generated on 2021-12-24 08:05:29 PM (MST).

Step 1 — 1: Main Assembly

- Please watch our install video here: https://www.youtube.com/watch?v=DTPmOsFY...

This document was generated on 2021-12-24 08:05:29 PM (MST).

© 2021   repkord.dozuki.com/   Page 3 of 3